


FIG._4




5 / 66 *1252* HAMMER OPERATING LEVER *1266* ZERO RETURN -EVER B SPRING 1264 HEART CAM B 1244 OPERATING LEVER SPRING 7 1265 ZERO RETURN LEVER B SECOND WHEEL - 1251 OPERATING LEVER 1243 SWITCH LEVER A 1256 HAMMER JUMPER 1242 OPERATING LEVER 1201 START/STOP BUTTON *1241* COLUMN WHEEL JUMPER - 1202 RESET BUTTON 1261 HEART CAM A 1267 HEART CAM C ھہ 8 HEART CAM D 1270 CG 1/10-SECOND WHEEL 1232 **CG MINUTE AND HOUR WHEEL 1216** ZERO RETURN LEVER A 1262 ZERO RETURN LEVER C SPRING 1269 SWITCH LEVER B 1257 -ZERO RETURN LEVER C 1268 -ZERO RETURN LEVER D SPRING 1272 -ZERO RETURN LEVER A SPRING *1263* -HAMMER DRIVING LEVER 1254 ZERO RETURN LEVER D *1271* – INTERMEDIATE HAMMER SPRING *1255* 1240a -1240b --**COLUMN WHEEL 1240 - -**CONTACT -RESET CIRCUIT INTERMEDIATE HAMMER 1253



































FIG._10










FIG._11








FIG._12
















FIG._14


















FIG._16


1P

FEB 1 3 2003

TRADEWIN'S












FIG._ 19
















THE 13 2000



+









FIG._26






































FIG._32

1202






FIG._33








FIG._34















FIG._36













FIG._38




38 / 66



+











FIG._42








FIG._44






FIG._45



44 / 66






FIG._46















FIG._49
















50 / 66




















FIG._55






FIG._56



1253a


1253b

1251b

1251a

-1202

P4469b, Serial No. 09/446,449 Customer No. 20178



1252a

1253c




FIG._57









FIG._58









FIG._59














FIG._61













P4469b, Serial No. 09/446,449 Customer No. 20178 63 / 66














FIG._67












FIG._69

RESET CONTROL SIGNAL SRC